



LG VX8300 Bluetooth Car Kit Support for Verizon Wireless Subscribers

**Notes:****"Do not Remove"**

1. If you do not see a specific auto manufacture listed for the desired VZW handset, please check with that auto manufacturer for compatibility information.
2. Information regarding Bluetooth(R) capabilities for the cars listed below has been provided by the handset manufacturer, and has not been independently verified by Verizon Wireless.

Device Model # H/W S/W version(s)	Car Manufacturer	Car Model	BT Car Kit OEM	Functionality										Comments
				BT Connection	RX / TX Audio	SEND / END	Rings	PB Transfer	Batt Meter	RSSI Meter	Roaming Status	Caller ID	Voice Recog	
Embedded OEM Bluetooth Car Kits														
VX8300 (HW:1.0) (SW: T83VZV03)	Acura	TL / RL	JCI	Yes	Yes	Yes	Yes	n/a	Yes	Yes	Yes	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Audi 2005-2006	A3 - A8	Temik (HarmanBecker)	Yes	Yes	Yes	Yes	Yes	n/a	Yes	Yes	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Chrysler	All models with factory installed kits	JCI	Yes	Yes	Yes	Yes	n/a	Yes	Yes	Yes	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Chrysler	All models with factory installed kits	Peiker	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Ford	Dealer installed kit	Peiker	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	GM	STS navigation	Denso	Yes*	Yes	Yes	Yes**	Yes	Yes	Yes	Yes	Yes	c/i	*Only when it's searched by the phone. ** Inband ringtone not supported by VX8550 due to Qualcomm limitations.
VX8300 (HW:1.0) (SW: T83VZV03)	Honda	All models with factory installed kits	JCI	Yes	Yes	Yes	Yes	n/a	Yes	Yes	Yes	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Infiniti 2006	QX56	Visteon	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Infiniti 2005-2006	M35 M45	Xanavi (Hitachi)	Yes	Yes	Yes	Yes	Yes	n/a	Yes	n/a	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Lexus	All models with factory installed kits	Denso	Yes	Yes	Yes	Yes**	Yes	Yes	Yes	Yes	Yes	c/i	** Inband ringtone not supported by VX8550 due to Qualcomm limitations.
VX8300 (HW:1.0) (SW: T83VZV03)	Lincoln	All models with factory installed kits	Peiker	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Nissan 2006	All models with factory installed kits	Visteon	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Renault 2005-2006	Laguna	Xanavi (Hitachi)	Yes	Yes	Yes	Yes	Yes	n/a	Yes	n/a	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Jaguar 2003 - 2005	XJ 2004MY and up XK 2003MY and up S-Type 2003MY and up X-Type 2003MY and up	Motorola	Yes	Yes	Yes	Yes	Yes	n/a	n/a	n/a	Yes	c/i	
VX8300 (HW:1.0) (SW: T83VZV03)	Toyota	All models with factory installed kits	Denso	Yes	Yes	Yes	Yes**	Yes	Yes	Yes	Yes	n/a	c/i	** Inband ringtone not supported by VX8550 due to Qualcomm limitations.
Aftermarket Bluetooth Car Kits														
VX8300 (HW:1.0) (SW: T83VZV03)	N/A	N/A	Motorola Car Kit II (HF850)	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	Yes	
VX8300 (HW:1.0) (SW: T83VZV03)	N/A	N/A	Motorola ACES Aftermarket (IHF1000)	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	Yes	Yes	
VX8300 (HW:1.0) (SW: T83VZV03)	N/A	N/A	Sony Ericsson HCB30	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	n/a	Yes	
VX8300 (HW:1.0) (SW: T83VZV03)	N/A	N/A	LG Visor	Yes	Yes	Yes	Yes	n/a	n/a	n/a	n/a	Yes	Yes	

Yes = Supported
 N/A = Functionality not supported by the Car Kit and/or Device over Bluetooth
 C/I = Functionality internal to the Car Kit only. Handset functionality is not utilized.
 Pending = Pending Test Verification